

**Mary Crowther Park Changing Rooms and Toilets
101N Wise Street, Wainuiomata**

Initial Seismic Assessment

**for
Hutt City Council**



Project 9793

April 2020

9792
9 April 2020
Private Bag 31912
Lower Hutt 5040

Attention: Aaron Marsh

Dear Aaron,

Initial Seismic Assessment Report
Mary Crowther Park Changing Rooms and Toilets, 101N Wise Street, Wainuiomata

We have now completed an Initial Seismic Assessment (ISA) of the changing rooms and toilets building at Mary Crowther Park, 101N Wise Street, Wainuiomata using the Initial Evaluation Procedure (IEP) as described in Part B of the guideline document, *The Seismic Assessment of Existing Buildings-Technical Guidelines for Engineering Assessments*, dated August 2017. The assessment was carried out after completing a site visit on Wednesday 25 March 2020.

Executive Summary

This building has been rated against the new building standard for a normal structure which is regarded as Importance Level 2 (IL2) in accordance with NZS1170.5:2004.

The assessed potential earthquake rating is 34%NBS (IL2) in both the longitudinal and transverse directions, which gives it a seismic 'Grade C'. Therefore, the potential status of the building in terms of life-safety is Earthquake Risk and not Earthquake Prone.

A "Severe Structural Weakness" (SSW) is a structural weakness for which rupture would lead to a catastrophic collapse. No Severe Structural Weaknesses have been identified.

The Initial Seismic Assessment (ISA) is considered to provide a relatively quick, high-level and qualitative measure of the building's performance. A more reliable result would be obtained from a Detailed Seismic Assessment (DSA). A DSA could find structural aspects of concern that have not been identified from the IEP. Alternatively, a detailed structural assessment may show that structural aspects of potential concern identified in this IEP may have in fact been addressed in the design of the building.

Introduction

Hutt City Council has engaged Sawrey Consulting Engineers Ltd (SCEL) to carry out an Initial Seismic Assessment (ISA) of the changing rooms and toilets building at Mary Crowther Park, located at 101N Wise Street, Wainuiomata, Lower Hutt. This ISA is based on the Initial Evaluation Procedure (IEP) as defined in *Technical Guidelines for Engineering Assessments* referenced above.

Earthquake Prone Building (EPB) methodology is used to identify earthquake-prone buildings, and has been produced by the Ministry of Business, Innovation and Employment in accordance with the Building Act 2004. This ISA meets the requirements of an engineering assessment as prescribed in the EPB methodology.

Background to the IEP and Its Limitations

The IEP procedure was developed in 2006 by the New Zealand Society for Earthquake Engineering (NZSEE) and updated in 2017 to reflect experience with its application and also as a result of experience from the Canterbury earthquakes of 2010/11. It is a tool to assign a percentage of New Building Standard (%NBS) rating and associated grade to a building as part of an Initial Seismic Assessment of existing buildings.

The IEP enables building owners and managers to review their building stock as part of an overall risk management process.

Characteristics and limitations of the IEP include:

- An IEP assessment is primarily concerned with life safety. It does not consider the susceptibility of the building to damage, and therefore to economic losses.
- It tends to be somewhat conservative, identifying some buildings as earthquake prone, or having a lower %NBS score, which subsequent detailed investigation may indicate is less than actual performance. However, there will be exceptions, particularly when potential critical structural weaknesses (CSWs) are present that have not been recognised from the level of investigation employed.
- An IEP can be undertaken with variable levels of available information: e.g. exterior only inspection, structural drawings available or not, interior inspection, etc. The more information available, the more representative the IEP result is likely to be. The IEP records the information that has formed the basis of the assessment and consideration of this is important when determining the likely reliability of the result.
- It is an initial, first-stage review. Buildings or specific issues which the IEP process flags as being problematic or as potentially critical structural weaknesses need further detailed investigation and evaluation. A Detailed Seismic Assessment is recommended if the seismic status of a building is critical to any decision making.
- The IEP assumes that buildings have been designed and built in accordance with the building standard and good practice current at the time. In some instances, a building may include design features ahead of its time, leading to better than predicted performance. Conversely, some unidentified design or construction issues not picked up by the IEP process may result in the building performing not as well as predicted.

- It is a largely qualitative process and should be undertaken or overseen by an experienced engineer. It involves considerable knowledge of the earthquake behaviour of buildings, and judgement as to key attributes and their effect on building performance. Consequently, it is possible that the %NBS derived for a building by independent experienced engineers may differ.
- An IEP may over-penalise some apparently critical features which could have been satisfactorily taken into account in the design.
- An IEP does not take into account the seismic performance of non-structural items such as ceilings, plant, services or general glazing that are not considered to present a significant life safety hazard.

Experience to date is that the IEP is a useful tool to identify potential issues and expected overall performance of a building in an earthquake. However, the process and the associated %NBS rating and grade should be considered as only providing an indication of the building's compliance with current code requirements. A detailed investigation and analysis of the building will typically be required to provide a definitive assessment.

Basis for the Assessment

The information we have used for our IEP assessment includes:

- The building appears to have been constructed in 1969.
- Subsoil class D has been used based on GNS Science's Lower Hutt Valley Site Subsoil Class Map and our engineering judgment.
- The period has been determined as being less than 0.40 seconds, based on the reinforced masonry shear wall structure.
- A Hazard Scaling Factor of $Z = 0.4$ has been used based on the location of the site in Wainuiomata.
- The building has been assumed to have an Importance Level 2 (normal structures).
- A ductility factor of $\mu = 2.0$ has been assumed based on the reinforced masonry shear wall structure.

The key assumptions made during our assessment are shown in Table 1 that follows.

Table 1: IEP Assumptions

IEP Item	Assumption	Justification
Date of Building Design	1969	Date of Building Permit
Soil Type	D	GNS Science's Lower Hutt Valley Site Subsoil Class Map and our engineering judgment
Building Importance Level	2	AS/NZS1170.0
Ductility of Structure	2.0	Reinforced masonry shear wall structure.
Plan Irregularity Factor, A	1.0	Insignificant
Vertical Irregularity Factor, B	1.0	Insignificant
Short Columns Factor, C	1.0	Insignificant
Pounding Factor, D	1.0	Insignificant
Site Characteristics	1.0	Insignificant – Greater Wellington GIS viewer indicates site is on the border between low and moderate liquefaction potential
Factor F	1.0	Building is in reasonable condition. Single storey with well distributed shear walls. Calculations carried out to check block walls out-of-plane and columns cantilevering above block walls using relatively conservative assumptions for reinforcement due to lack of available drawings to review.

Building Description

The building is single storey and appears to have been constructed in 1969 (based on the date of the building permit issued). No drawings were available for perusal.

The roof is monoslope, with corrugated iron supported on timber purlins, which in turn are supported by steel I-beams. The steel I-beams span the width of the building and are supported by 300mm x 300mm concrete columns. There are eight columns in total - four on each side of the building. At the high side of the building, the columns cantilever approximately 800mm above the top of the block walls and there are clerestorey windows above the block walls between the columns.

The external walls are 190mm thick blockwork between the concrete columns. The internal walls are a mix of 190mm and 140mm thick blockwork. Some of the block walls have returns, but others do not and are vertical cantilevers.

There is a concrete floor slab. It is assumed the foundations consist of shallow footings.

IEP Assessment Result

Our IEP assessment of this building indicates the building achieves 34%NBS (IL2) in both the longitudinal and transverse directions. The IEP assessment of this building therefore indicates an overall earthquake rating of 34%NBS (IL2), corresponding to a 'Grade C' building as defined by the New Zealand Society for Earthquake Engineering (NZSEE) building grading scheme. This is above the threshold for Earthquake Prone Buildings (34%NBS), but below the threshold for Earthquake Risk Buildings (67%NBS) as recommended by the NZSEE.

The key assumptions made during our assessment are shown in Table 1 above. Refer also to the attached IEP assessment and ISA technical summary report.

IEP Grades and Relative Risk

NZSEE (which provides authoritative advice to the legislation makers and should be considered to represent the consensus view of New Zealand structural engineers) classifies buildings achieving greater than 67%NBS as "low or medium risk" and having "acceptable (improvement may be desirable)" building structural performance.

Table 2 taken from the Technical Guidelines referred to earlier provides the basis for a proposed grading system for existing buildings, as one way of interpreting the %NBS earthquake rating.

This building has been classified by the IEP as a 'Grade C' building and is therefore considered to be a medium life-safety risk.

Table 2: Relative Earthquake Risk

Building Grade	Percentage of New Building Strength (%NBS)	Approx. Risk Relative to a New Building	Life-safety Risk Description
A+	>100	<1	low risk
A	80 to 100	1 to 2 times	low risk
B	67 to 79	2 to 5 times	low or medium risk
C	34 to 66	5 to 10 times	medium risk
D	20 to 33	10 to 25 times	high risk
E	<20	more than 25 times	very high risk

Seismic Restraint of Non-Structural Items

During an earthquake, the safety of people can be put at risk due to non-structural items falling on them. These items should be adequately seismically restrained, where possible, to the NZS 4219:2009 "The Seismic Performance of Engineering Systems in Buildings".

An assessment has not been made of bracing of the ceilings, services and plant. We have also not checked whether tall or heavy furniture has been seismically restrained or not. These issues are outside the scope of this initial assessment but could be the subject of another investigation.

Conclusion

Our ISA assessment for this building, carried out using the IEP indicates an overall score of 34%NBS (IL2), which corresponds to a 'Grade C' building, as defined by the NZSEE building grading scheme. This is above the threshold for Earthquake Prone Buildings (34%NBS), but below the threshold for Earthquake Risk Buildings (67%NBS) as recommended by the NZSEE.

The ISA is considered to provide a relatively quick, high-level and qualitative measure of the building's performance. In order to confirm the seismic performance of this building with more reliability you may wish to request a Detailed Seismic Assessment (DSA).


A DSA would also investigate other potential weaknesses that may not have been considered in the initial seismic assessment.

We note that a geotechnical desktop study would be required as part of a DSA.

We trust this letter and initial seismic assessment meets your current requirements. We would be pleased to discuss further with you any issues raised in this report. Please do not hesitate to contact us if you would like clarification of any aspect of this letter.

Yours faithfully

SAWREY CONSULTING ENGINEERS LTD



Appendix A: ISA Technical Summary Report

Appendix B: IEP Form

Appendix A - ISA Technical Summary Report

1. Building Information	
Building Name/ Description	Mary Crowther Park Changing Rooms and Toilets
Street Address	101N Wise Street, Wainuiomata
Territorial Authority	Hutt City Council
No. of Storeys	1
Area of Typical Floor (approx.)	135m ²
Year of Design (approx.)	1969
NZ Standards designed to	NZSS 1900:1965
Structural System including Foundations	<p>Monoslope roof with corrugated iron supported on timber purlins, which in turn are supported by steel I-beams. The steel I-beams span the width of the building and are supported by 300mm x 300mm concrete columns. There are eight columns in total - four on each side of the building. At the high side of the building, the columns cantilever approximately 800mm above the top of the block walls and there are clerestorey windows above the block walls between the columns.</p> <p>The external walls are 190mm thick blockwork between the concrete columns. The internal walls are a mix of 190mm and 140mm thick blockwork. Some of the block walls have returns, but others do no and are vertical cantilevers.</p> <p>Concrete floor slab. It is assumed the foundations consist of shallow footings.</p>
Does the building comprise a shared structural form or shares structural elements with any other adjacent titles?	No
Key features of ground profile and identified geohazards	Low to moderate liquefaction potential
Previous strengthening and/ or significant alteration	N/A
Heritage Issues/ Status	None
Other Relevant Information	N/A

2. Assessment Information	
Consulting Practice	Sawrey Consulting Engineers Ltd
CPEng Responsible, including: <ul style="list-style-type: none"> • Name • CPEng number • A statement of suitable skills and experience in the seismic assessment of existing buildings [1] 	<div style="background-color: black; width: 100px; height: 15px; margin-bottom: 5px;"></div> <div style="background-color: black; width: 200px; height: 15px; margin-bottom: 5px; margin-left: 20px;"></div> <div style="background-color: black; width: 700px; height: 15px; margin-bottom: 5px; margin-left: 20px;"></div> <div style="background-color: black; width: 300px; height: 15px; margin-bottom: 5px; margin-left: 20px;"></div> <div style="background-color: black; width: 650px; height: 15px; margin-bottom: 5px; margin-left: 20px;"></div> <div style="background-color: black; width: 680px; height: 15px; margin-bottom: 5px; margin-left: 20px;"></div>
Documentation reviewed, including: <ul style="list-style-type: none"> • date/ version of drawings/ calculations [2] • previous seismic assessments 	No drawings available for perusal
Geotechnical Report(s)	None
Date(s) Building Inspected and extent of inspection	Inspection of accessible exterior and interior parts of building completed on Wednesday 25 th March 2020
Description of any structural testing undertaken and results summary	None
Previous Assessment Reports	None
Other Relevant Information	N/A

1 This should include reference to the engineer's Practice Field being in Structural Engineering, and commentary on experience in seismic assessment and recent relevant training

2 Or justification of assumptions if no drawings were able to be obtained

3. Summary of Engineering Assessment Methodology and Key Parameters Used	
Occupancy Type(s) and Importance Level	IL2
Site Subsoil Class	D
<u>For an ISA:</u>	
<p>Summary of how Part B was applied, including:</p> <ul style="list-style-type: none"> • Key parameters such as μ, S_p and F factors • Any supplementary specific calculations 	<ul style="list-style-type: none"> • μ of 2.0 based on reinforced masonry shear wall structure • S_p of 0.7 • F factor of 1.0 – Building is in reasonable condition. Single storey with well distributed shear walls. Calculations carried out to check block walls out-of-plane and columns cantilevering above block walls using relatively conservative assumptions for reinforcement due to lack of available drawings to review.
<u>For a DSA:</u>	
<p>Summary of how Part C was applied, including:</p> <ul style="list-style-type: none"> • the analysis methodology(s) used from C2 • other sections of Part C applied 	N/A
Other Relevant Information	N/A

4. Assessment Outcomes		
Assessment Status (Draft or Final)	Final	
Assessed %NBS Rating	34% NBS (IL2)	
Seismic Grade and Relative Risk (from Table A3.1)	C	
For an ISA:		
Describe the Potential Critical Structural Weaknesses	<ul style="list-style-type: none"> Reinforced masonry walls out-of-plane 	
Does the result reflect the building's expected behaviour, or is more information/ analysis required?	Yes – the ISA is sufficient Or No – a DSA is recommended [3]	
If the results of this ISA are being used for earthquake prone decision purposes, <u>and</u> elements rating <34%NBS have been identified:	Engineering Statement of Structural Weaknesses and Location	Mode of Failure and Physical Consequence Statement(s)
	N/A	N/A
For a DSA:		
Comment on the nature of Secondary Structural and Non-structural elements/ parts identified and assessed	N/A	
Describe the Governing Critical Structural Weakness	N/A	
If the results of this DSA are being used for earthquake prone decision purposes, <u>and</u> elements rating <34%NBS have been identified (including Parts) [4]:	Engineering Statement of Structural Weaknesses and Location	Mode of Failure and Physical Consequence Statement(s)
	N/A	N/A
Recommendations (optional for EPB purposes)	N/A	

3 Indicate what form should the DSA take/ what the specific areas to focus on are

4 If a building comprises a shared structural form or shares structural elements with other adjacent titles, information about the extent to which the low scoring elements affect, or do not affect the structure.

Appendix B – Initial Evaluation Procedure (IEP)

Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in the "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Street Number & Name:	101N Wise Street	Job No.:	9793
AKA:		By:	
Name of building:	Mary Crowther Park Changing Rooms and Toilets	Date:	7/04/2020
City:	Wainuiomata, Lower Hutt	Revision No.:	0

Table IEP-1 Initial Evaluation Procedure Step 1


Step 1 - General Information

1.1 Photos (attach sufficient to describe building)



NOTE: THERE ARE MORE PHOTOS ON PAGE 1a ATTACHED

1.2 Sketches (plans etc, show items of interest)



NOTE: THERE ARE MORE SKETCHES ON PAGE 1a ATTACHED

1.3 List relevant features (Note: only 10 lines of text will print in this box. If further text required use Page 1a)

The building is single storey and appears to have been constructed in 1969.

The roof is monoslope, with corrugated iron supported on timber purlins, which in turn are supported by steel I-beams. The steel I-beams span the width of the building and are supported by 300mm x 300mm concrete columns. There are eight columns in total - four on each side of the building. At the high side of the building, the columns cantilever approximately 800mm above the top of the block walls and there are clerestory windows above the block walls between the columns.

The external walls are 190mm thick blockwork between the concrete columns. The internal walls are a mix of 190mm and 140mm thick blockwork. Some of the block walls have returns, but others do not and are vertical cantilevers.

There is a concrete floor slab. It is assumed the foundations consist of shallow footings.

1.4 Note information sources

Tick as appropriate

Visual Inspection of Exterior	<input checked="" type="checkbox"/>
Visual Inspection of Interior	<input checked="" type="checkbox"/>
Drawings (note type)	<input type="checkbox"/>

Specifications	<input type="checkbox"/>
Geotechnical Reports	<input type="checkbox"/>
Other (list)	<input type="checkbox"/>

No drawings available for perusal.

Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

Street Number & Name:	101N Wise Street	Job No.:	9793
AKA:		By:	
Name of building:	Mary Crowther Park Changing Rooms and Toilets	Date:	7/04/2020
City:	Wainuiomata, Lower Hutt	Revision No.:	0

Table IEP-1a Additional Photos and Sketches

Add any additional photographs, notes or sketches required below:

Note: print this page separately



WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

Street Number & Name:	101N Wise Street	Job No.:	9793
AKA:		By:	
Name of building:	Mary Crowther Park Changing Rooms and Toilets	Date:	7/04/2020
City:	Wainuiomata, Lower Hutt	Revision No.:	0

Table IEP-2 Initial Evaluation Procedure Step 2

Step 2 - Determination of (%NBS)_b

(Baseline (%NBS) for particular building - refer Section B5)

2.1 Determine nominal (%NBS) = (%NBS)_{nom}

	<u>Longitudinal</u>	<u>Transverse</u>
a) Building Strengthening Data		
Tick if building is known to have been strengthened in this direction	<input type="checkbox"/>	<input type="checkbox"/>
If strengthened, enter percentage of code the building has been strengthened to	N/A	N/A
b) Year of Design/Strengthening, Building Type and Seismic Zone		
	Pre 1935 <input type="radio"/>	Pre 1935 <input type="radio"/>
	1935-1965 <input type="radio"/>	1935-1965 <input type="radio"/>
	1965-1976 <input checked="" type="radio"/>	1965-1976 <input checked="" type="radio"/>
	1976-1984 <input type="radio"/>	1976-1984 <input type="radio"/>
	1984-1992 <input type="radio"/>	1984-1992 <input type="radio"/>
	1992-2004 <input type="radio"/>	1992-2004 <input type="radio"/>
	2004-2011 <input type="radio"/>	2004-2011 <input type="radio"/>
	Post Aug 2011 <input type="radio"/>	Post Aug 2011 <input type="radio"/>
Building Type:	Others	Others
Seismic Zone:	Zone A	Zone A
c) Soil Type		
From NZS1170.5:2004, CI 3.1.3 :	D Soft Soil	D Soft Soil
From NZS4203:1992, CI 4.6.2.2 : (for 1992 to 2004 and only if known)	Not applicable	Not applicable
d) Estimate Period, T		
<i>Comment:</i>	$h_n = 4$	4 m
	$A_c = 1.00$	1.00 m ²
Moment Resisting Concrete Frames: $T = \max\{0.09h_n^{0.75}, 0.4\}$	<input type="radio"/>	<input type="radio"/>
Moment Resisting Steel Frames: $T = \max\{0.14h_n^{0.75}, 0.4\}$	<input type="radio"/>	<input type="radio"/>
Eccentrically Braced Steel Frames: $T = \max\{0.08h_n^{0.75}, 0.4\}$	<input type="radio"/>	<input type="radio"/>
All Other Frame Structures: $T = \max\{0.06h_n^{0.75}, 0.4\}$	<input type="radio"/>	<input type="radio"/>
Concrete Shear Walls: $T = \max\{0.09h_n^{0.75}/A_c^{0.5}, 0.4\}$	<input type="radio"/>	<input type="radio"/>
Masonry Shear Walls: $T \leq 0.4\text{sec}$	<input checked="" type="radio"/>	<input checked="" type="radio"/>
User Defined (input Period):	<input type="radio"/>	<input type="radio"/>
<i>Where h_n = height in metres from the base of the structure to the uppermost seismic weight or mass.</i>	T: 0.40	0.40
e) Factor A: Strengthening factor determined using result from (a) above (set to 1.0 if not strengthened)	Factor A: 1.00	1.00
f) Factor B: Determined from NZSEE Guidelines Figure 3A.1 using results (a) to (e) above	Factor B: 0.06	0.06
g) Factor C: For reinforced concrete buildings designed between 1976-84 Factor C = 1.2, otherwise take as 1.0.	Factor C: 1.00	1.00
h) Factor D: For buildings designed prior to 1935 Factor D = 0.8 except for Wellington and Napier (1931-1935) where Factor D may be taken as 1.0, otherwise take as 1.0.	Factor D: 1.00	1.00
(%NBS)_{nom} = AxBxCxD	(%NBS)_{nom} 6%	6%

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

Street Number & Name:	101N Wise Street	Job No.:	9793
AKA:		By:	
Name of building:	Mary Crowther Park Changing Rooms and Toilets	Date:	7/04/2020
City:	Wainuiomata, Lower Hutt	Revision No.:	0

Table IEP-2 Initial Evaluation Procedure Step 2 continued

2.2 Near Fault Scaling Factor, Factor E
If $T \leq 1.5\text{sec}$, Factor E = 1

	<u>Longitudinal</u>	<u>Transverse</u>
a) Near Fault Factor, $N(T,D)$ <small>(from NZS1170.5:2004, Cl 3.1.6)</small>	N(T,D): <input type="text" value="1"/>	<input type="text" value="1"/>
b) Factor E = $1/N(T,D)$	Factor E: <input type="text" value="1.00"/>	<input type="text" value="1.00"/>

2.3 Hazard Scaling Factor, Factor F

a) Hazard Factor, Z, for site

Location: Refer right for user-defined locations

Z = (from NZS1170.5:2004, Table 3.3)

Z₁₉₉₂ = (NZS4203:1992 Zone Factor from accompanying Figure 3.5(b))

Z₂₀₀₄ = (from NZS1170.5:2004, Table 3.3)

b) Factor F

For pre 1992 = $1/Z$

For 1992-2011 = Z_{1992}/Z

For post 2011 = Z_{2004}/Z

	<u>Longitudinal</u>	<u>Transverse</u>
Factor F:	<input type="text" value="2.50"/>	<input type="text" value="2.50"/>

2.4 Return Period Scaling Factor, Factor G

a) Design Importance Level, I
(Set to 1 if not known. For buildings designed prior to 1965 and known to be designed as a public building set to 1.25. For buildings designed 1965-1976 and known to be designed as a public building set to 1.33 for Zone A or 1.2 for Zone B. For 1976-1984 set I value.)

I =

b) Design Risk Factor, R₀
(set to 1.0 if other than 1976-2004, or not known)

R₀ =

c) Return Period Factor, R
(from NZS1170.0:2004 Building Importance Level) Choose Importance Level 1 2 3 4

R =

d) Factor G = IR_0/R

	<u>Longitudinal</u>	<u>Transverse</u>
Factor G:	<input type="text" value="1.00"/>	<input type="text" value="1.00"/>

2.5 Ductility Scaling Factor, Factor H

a) Available Displacement Ductility Within Existing Structure

Comment:

μ =

b) Factor H

For pre 1976 (maximum of 2) = $k_{\mu}/1.57$

For 1976 onwards = 1

Factor H:

(where k_{μ} is NZS1170.5:2004 Inelastic Spectrum Scaling Factor, from accompanying Table 3.3)

2.6 Structural Performance Scaling Factor, Factor I

a) Structural Performance Factor, S_p
(from accompanying Figure 3.4)
Tick if light timber-framed construction in this direction

S_p =

b) Structural Performance Scaling Factor = $1/S_p$

Note Factor B values for 1992 to 2004 have been multiplied by 0.67 to account for S_p in this period

	<u>Longitudinal</u>	<u>Transverse</u>
Factor I:	<input type="text" value="1.43"/>	<input type="text" value="1.43"/>

2.7 Baseline %NBS for Building, (%NBS)_b
(equals (%NBS)_{nom} x E x F x G x H x I)

	<u>Longitudinal</u>	<u>Transverse</u>
(%NBS) _b	<input type="text" value="34%"/>	<input type="text" value="34%"/>

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

Street Number & Name:	101N Wise Street	Job No.:	9793
AKA:		By:	
Name of building:	Mary Crowther Park Changing Rooms and Toilets	Date:	7/04/2020
City:	Wainuiomata, Lower Hutt	Revision No.:	0

Table IEP-3 Initial Evaluation Procedure Step 3

Step 3 - Assessment of Performance Achievement Ratio (PAR)

(Refer Appendix B - Section B3.2)

a) Longitudinal Direction

potential CSWs	Effect on Structural Performance (Choose a value - Do not interpolate)	Factors
3.1 Plan Irregularity	Effect on Structural Performance <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant	Factor A <input type="text" value="1.0"/>
3.2 Vertical Irregularity	Effect on Structural Performance <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant	Factor B <input type="text" value="1.0"/>
3.3 Short Columns	Effect on Structural Performance <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant	Factor C <input type="text" value="1.0"/>

3.4 Pounding Potential

(Estimate D1 and D2 and set D = the lower of the two, or 1.0 if no potential for pounding, or consequences are considered to be minimal)

a) Factor D1: - Pounding Effect

Note:
Values given assume the building has a frame structure. For stiff buildings (eg shear walls), the effect of pounding may be reduced by taking the coefficient to the right of the value applicable to frame buildings.

Factor D1 For Longitudinal Direction:

Table for Selection of Factor D1	Severe	Significant	Insignificant
	0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Alignment of Floors within 20% of Storey Height	<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8

b) Factor D2: - Height Difference Effect

Factor D2 For Longitudinal Direction:

Table for Selection of Factor D2	Severe	Significant	Insignificant
	0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Height Difference > 4 Storeys	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 1
Height Difference 2 to 4 Storeys	<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys	<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1

Factor D

3.5 Site Characteristics - Stability, landslide threat, liquefaction etc as it affects the structural performance from a life-safety perspective

Effect on Structural Performance <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant	Factor E <input type="text" value="1.0"/>
Greater Wellington GIS viewer indicates site is on the border between low and moderate liquefaction potential.	

3.6 Other Factors - for allowance of all other relevant characteristics of the building

For ≤ 3 storeys - Maximum value 2.5
otherwise - Maximum value 1.5.
No minimum.

Factor F

Record rationale for choice of Factor F:

Building is in reasonable condition. Single storey with well distributed shear walls. Calculations carried out to check block walls out-of-plane and columns cantilevering above block walls using relatively conservative assumptions for reinforcement due to lack of available drawings to review.

3.7 Performance Achievement Ratio (PAR)

(equals A x B x C x D x E x F)

PAR
Longitudinal

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

Street Number & Name:	101N Wise Street	Job No.:	9793
AKA:		By:	
Name of building:	Mary Crowther Park Changing Rooms and Toilets	Date:	7/04/2020
City:	Wainuiomata, Lower Hutt	Revision No.:	0

Table IEP-3 Initial Evaluation Procedure Step 3

Step 3 - Assessment of Performance Achievement Ratio (PAR)

(Refer Appendix B - Section B3.2)

b) Transverse Direction

potential CSWs	Effect on Structural Performance (Choose a value - Do not interpolate)	Factors
3.1 Plan Irregularity Effect on Structural Performance <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant		Factor A 1.0
3.2 Vertical Irregularity Effect on Structural Performance <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant		Factor B 1.0
3.3 Short Columns Effect on Structural Performance <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant		Factor C 1.0
3.4 Pounding Potential (Estimate D1 and D2 and set D = the lower of the two, or 1.0 if no potential for pounding, or consequences are considered to be minimal)		

a) Factor D1: - Pounding Effect

Note:
Values given assume the building has a frame structure. For stiff buildings (eg shear walls), the effect of pounding may be reduced by taking the coefficient to the right of the value applicable to frame buildings.

Factor D1 For Transverse Direction: 1.0

Table for Selection of Factor D1	Severe 0<Sep<.005H	Significant .005<Sep<.01H	Insignificant Sep>.01H
Alignment of Floors within 20% of Storey Height	<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8

b) Factor D2: - Height Difference Effect

Factor D2 For Transverse Direction: 1.0

Table for Selection of Factor D2	Severe 0<Sep<.005H	Significant .005<Sep<.01H	Insignificant Sep>.01H
Height Difference > 4 Storeys	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 1
Height Difference 2 to 4 Storeys	<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys	<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1

Factor D 1.0

3.5 Site Characteristics - Stability, landslide threat, liquefaction etc as it affects the structural performance from a life-safety perspective

Effect on Structural Performance <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant	Factor E 1.0
Greater Wellington GIS viewer indicates site is on the border between low and moderate liquefaction potential.	

3.6 Other Factors - for allowance of all other relevant characteristics of the building

Record rationale for choice of Factor F: Building is in reasonable condition. Single storey with well distributed shear walls. Calculations carried out to check block walls out-of-plane and columns cantilevering above block walls using relatively conservative assumptions for reinforcement due to lack of available drawings to review.	For ≤ 3 storeys - Maximum value 2.5 otherwise - Maximum value 1.5. No minimum.	Factor F 1.00
--	--	----------------------

3.7 Performance Achievement Ratio (PAR)

(equals A x B x C x D x E x F)

PAR
Transverse 1.00

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

Street Number & Name:	101N Wise Street	Job No.:	9793
AKA:		By:	
Name of building:	Mary Crowther Park Changing Rooms and Toilets	Date:	7/04/2020
City:	Wainuiomata, Lower Hutt	Revision No.:	0

Table IEP-4 Initial Evaluation Procedure Steps 4, 5, 6 and 7

Step 4 - Percentage of New Building Standard (%NBS)

	Longitudinal	Transverse
4.1 Assessed Baseline %NBS (%NBS) _b (from Table IEP - 1)	34%	34%
4.2 Performance Achievement Ratio (PAR) (from Table IEP - 2)	1.00	1.00
4.3 PAR x Baseline (%NBS) _b	34%	34%
4.4 Percentage New Building Standard (%NBS) - Seismic Rating (Use lower of two values from Step 4.3)		34%

Step 5 - Is %NBS < 34?

NO

Step 6 - Potentially Earthquake Risk (is %NBS < 67)?

YES

Step 7 - Provisional Grading for Seismic Risk based on IEP

Seismic Grade **C**

Additional Comments (items of note affecting IEP based seismic rating)

Relationship between Grade and %NBS:

Grade:	A+	A	B	C	D	E
%NBS:	> 100	100 to 80	79 to 67	66 to 34	< 34 to 20	< 20

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

Street Number & Name:	101N Wise Street	Job No.:	9793
AKA:		By:	
Name of building:	Mary Crowther Park Changing Rooms and Toilets	Date:	7/04/2020
City:	Wainuiomata, Lower Hutt	Revision No.:	0

Table IEP-5 Initial Evaluation Procedure Step 8

Step 8 - Identification of potential Severe Structural Weaknesses (SSWs) that could result in significant risk to a significant number of occupants

- 8.1 Number of storeys above ground level
- 8.2 Presence of heavy concrete floors and/or concrete roof? (Y/N)

Potential Severe Structural Weaknesses (SSWs):

Note: Options that are greyed out are not applicable and need not be considered.

Occupancy not considered to be significant - no further consideration required

Risk not considered to be significant - no further consideration required

The following potential Severe Structural Weaknesses (SSWs) have been identified in the building that could result in significant risk to a significant number of occupants:

- 1. None identified
- 2. Weak or soft storey (except top storey)
- 3. Brittle columns and/or beam-column joints the deformations of which are not constrained by other structural elements
- 4. Flat slab buildings with lateral capacity reliant on low ductility slab-to-column connections
- 5. No identifiable connection between primary structure and diaphragms
- 6. Ledge and gap stairs

IEP Assessment Confirmed by



WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.