

Executive summary

We have now completed an Initial Seismic Assessment (ISA) of Wainuiomata Library at Queen Street, Wainuiomata using the Initial Evaluation Procedure (IEP). The assessment was carried out after completing a site visit and an inspection of the building consent documentation.

Wainuiomata Library was designed and built circa 1983. This library is a single-storey timber-framed building with Pryda-speedbrace wall bracing panels. The building is currently used as a library and office space. This building has been subject to an Initial Seismic Assessment (ISA).

The building was found to have a potential compliance rating of 100% (IL2) of a new building built to current standards (NBS).

As the potential performance of the building is greater than 33% NBS ***this building should not be considered as potentially Earthquake Prone.***

The ISA is considered to provide a relatively quick, high-level and qualitative measure of the building's performance. A more reliable result will be obtained from a Detailed Seismic Assessment (DSA). A DSA could find Critical Structural Weaknesses (CSWs) not identified from the IEP, or it could find potential CSWs have been addressed in the design of the building. However the building is a single-level structure with lightweight construction and in good details, a DSA is identified as a low priority for this building.

This report is subject to, and must be read in conjunction with, the limitations set out in section 1.4 and the assumptions and qualifications contained throughout the Report.

Table of contents

1.	Introduction	3
1.1	Purpose of this report	3
1.2	Assessment Methodology.....	3
1.3	Scope and limitations	5
2.	Building History	6
2.1	Reference Documents.....	6
2.2	Structural System	6
2.3	Vulnerabilities.....	8
3.	Assessment Calculations	8
3.1	Calculation Summary	8
3.2	IEP Grades and Relative Risk	9
3.3	Seismic Restraint of Non-Structural Items.....	10
4.	Recommendations	10

Table index

Table 1 – IEP Parameters and Assumptions.....	9
Table 2: Relative Earthquake Risk.....	10
Table 3 – Assessment Information	12
Table 4 – Structural System Summary for Wainuiomata Library.....	13

Figure index

Figure 1 Building location	6
Figure 2 Location of the timber shear walls in the longitudinal direction.....	7
Figure 3 Location of the timber shear walls in the transverse direction	7
Figure 4 Location of steel portal frames.....	8

Appendices

Appendix A – Structural System Summary

Appendix B Initial Evaluation Form

1. Introduction

1.1 Purpose of this report

This assessment has been carried out at the request of the building owner, Hutt City Council, as part of their program of seismic assessments of community facilities.

1.2 Assessment Methodology

The IEP procedure was developed in 2006 by the New Zealand Society for Earthquake Engineering (NZSEE) and updated in 2013 to reflect experience with its application and as a result of experience in the Canterbury earthquakes. It is a tool to assign a percentage of New Building Standard (%NBS) score and associated grade to a building as part of an initial seismic assessment of existing buildings.

The IEP enables territorial authorities, building owners and managers to review their building stock as part of an overall risk management process.

Characteristics and limitations of the IEP include:

- An IEP assessment is primarily concerned with life safety. It does not consider the susceptibility of the building to damage, and therefore to economic losses.
- It tends to be somewhat conservative, identifying some buildings as earthquake prone, or having a lower %NBS score, which subsequent detailed investigation may indicate is less than actual performance. However, there will be exceptions, particularly when potential critical structural weaknesses (CSWs) are present that have not been recognised from the level of investigation employed.
- An IEP can be undertaken with variable levels of available information: e.g. exterior only inspection, structural drawings available or not, interior inspection, etc. The more information available, the more representative the IEP result is likely to be. The IEP records the information that has formed the basis of the assessment and consideration of this is important when determining the likely reliability of the result.
- It is an initial, first-stage review. Buildings or specific issues which the IEP process flags as being problematic or as potentially critical structural weaknesses need further detailed investigation and evaluation. A Detailed Seismic Assessment is recommended if the seismic status of a building is critical to any decision making.
- The IEP assumes that buildings have been designed and built in accordance with the building standard and good practice current at the time. In some instances, a building may include design features ahead of its time, leading to better than predicted performance. Conversely, some unidentified design or construction issues not picked up by the IEP process may result in the building performing not as well as predicted.
- It is a largely qualitative process, and should be undertaken or overseen by an experienced engineer. It involves considerable knowledge of the earthquake behaviour of buildings, and judgement as to key attributes and their effect on building performance. Consequently, it is possible that the %NBS derived for a building by independent experienced engineers may differ.
- An IEP may over-penalise some apparently critical features which could have been satisfactorily taken into account in the design.

- An IEP does not take into account the seismic performance of non-structural items such as ceilings, plant, services or general glazing that are not considered to present a significant life safety hazard.

Experience to date is that the IEP is a useful tool to identify potential issues and expected overall performance of a building in an earthquake. However, the process and the associated %NBS and grade should be considered as only indicative of the building's compliance with current code requirements. A detailed investigation and analysis of the building will typically be required to provide a definitive assessment.

An IEP score above 34%NBS should be considered sufficient to classify the building as not potentially earthquake prone. However, if further information comes available reassessment may be required.

Council Policies and Earthquake Prone Buildings (EPB)

The Building Act and its provisions for Earthquake Prone Buildings have been revised in April 2016 and enacted in July 2107. Some of the changes include nationalizing the policies to reduce regional variation and to create a distinction between different building types. The current time frame for assessment of building in the HCC area is 5 years based on the new legislation came into force on 1 July 2017.

1.3 Scope and limitations

This report: has been prepared by [REDACTED] for Hutt City Council and may only be used and relied on by Hutt City Council for the purpose agreed between [REDACTED] and the Hutt City Council as set out in section 1 of this report.

[REDACTED] otherwise disclaims responsibility to any person other than Hutt City Council arising in connection with this report. [REDACTED] also excludes implied warranties and conditions, to the extent legally permissible.

The services undertaken by [REDACTED] in connection with preparing this report were limited to those specifically detailed in the report and are subject to the scope limitations set out in the report.

The opinions, conclusions and any recommendations in this report are based on conditions encountered and information reviewed at the date of preparation of the report. [REDACTED] has no responsibility or obligation to update this report to account for events or changes occurring subsequent to the date that the report was prepared.

The opinions, conclusions and any recommendations in this report are based on assumptions made by [REDACTED] described in this report. [REDACTED] disclaims liability arising from any of the assumptions being incorrect.

[REDACTED] has prepared this report on the basis of information provided by Hutt City Council and others who provided information to [REDACTED] (including Government authorities)], which [REDACTED] has not independently verified or checked beyond the agreed scope of work. [REDACTED] does not accept liability in connection with such unverified information, including errors and omissions in the report which were caused by errors or omissions in that information.

The opinions, conclusions and any recommendations in this report are based on information obtained from, and testing undertaken at or in connection with, specific sample points. Site conditions at other parts of the site may be different from the site conditions found at the specific sample points.

Investigations undertaken in respect of this report are constrained by the particular site conditions, such as the location of buildings, services and vegetation. As a result, not all relevant site features and conditions may have been identified in this report.

Site conditions (including the presence of hazardous substances and/or site contamination) may change after the date of this Report. [REDACTED] does not accept responsibility arising from, or in connection with, any change to the site conditions. [REDACTED] is also not responsible for updating this report if the site conditions change.

2. Building History

2.1 Reference Documents

At your request, we have inspected the plans and available building consent records for this building, visited the site, and carried out an assessment for the earthquake risk aspects.

The information we have used for our IEP assessment includes:

- Structural drawings
- Exterior & interior inspection
- GNS Wellington Region Site Subsoil Maps

The building on the site is as identified below:




Figure 1 Building location

2.2 Structural System

Wainuiomata Library is a single-storey timber-framed building, which was designed and constructed circa 1983. Alterations to the internal layout of the building were carried out in 1995 and 2015. The 1995 alteration consists of constructing a ramp to improve the accessibility to the building, and removal of a number of timber walls (these were replaced with steel lintels and SHS columns). A small lobby was also added to the North-East side of the building in 2015.

The building is of timber-framed construction with bracing wall panels in both the transverse and longitudinal directions. The external wall cladding is a combination of fibre-cement sheet cladding and brick veneer. The roof is of lightweight timber truss construction with steel strap bracing (Pryda-speedbrace). The building foundation is comprised of a slab on grade.

When the structure is subjected to seismic action, the inertial loads from the roof and walls are transferred through the timber shear walls down to the foundation. The in-plane shear walls resist these loads through bending and yielding of the nail fixings around the perimeter of the wall. The locations of shear walls (parallel to the direction of seismic action) are shown in Figure 2 and 3 below.




Figure 2 Location of the timber shear walls in the longitudinal direction




Figure 3 Location of the timber shear walls in the transverse direction

Three Steel portal frames are located in the council chamber in the South-West corner of the building to provide resistance in the transverse direction. Refer to Figure 4 for the location of the portal frames.




Figure 4 Location of steel portal frames

Generally the interior of the Wainuiomata Library appeared to be in good condition. There were only cosmetic cracks observed at the plasterboard sheet joints in the wall lining.

This system is summarised further in Appendix 1 – structural system

2.3 Vulnerabilities

2.3.1 Plan Irregularity

The regularity of a building shape affects the way that a building can respond to lateral loading. As shown in Figure 1, the building is asymmetric in plan, and it is approximately a T-shape building. However, according to NZSEE Guideline, the effect from plan irregularity on timber-framed building can be assumed to be insignificant.

2.3.2 Brick Veneer Wall Cladding

The brick veneer wall cladding appears to be in good condition, with no obvious signs of cracks or damage. It is recommended to carry out further investigation to confirm the types and locations of the brick ties if a DSA is required.

3. Assessment Calculations

3.1 Calculation Summary

The key assumptions made during our assessment are shown in Table 1 Refer also to the attached IEP assessment.

Table 1 – IEP Parameters and Assumptions

IEP Item	Assumption	Justification
Date of building Design	1983	The building was designed circa 1983. Alterations to the building interior were carried out in 1995 and 2015.
Subsoil Type	D	Based on GNS Wellington Region Site Subsoil Maps
Ductility of structure	2.0	Timber frame building
Plan irregularity factor, A	1.0 (Both dir.)	The building is asymmetric in plan, and it is approximately a T-shape building. However, refer to the technical guidelines of The Seismic Assessment of Existing Buildings, plan irregularity is assumed to be insignificant for timber-framed building.
Vertical irregularity factor, B	1.0 (Both dir.)	No irregularity as the building is a single-storey building.
Short columns factor, C	1.0 (Both dir.)	N/A
Pounding factor, D	1.0 (Both dir.)	Refer to IEP report for further details.
Site characteristic	Insignificant	GNS Wellington Region Liquefaction Map shows that moderate liquefaction risk for this site. However, the building is considered as resilient structure type for liquefaction event, as it is a single-storey building.
F factor	1.0 (Both dir.)	Based on our inspection and review of available documents, the building is a single-storey timber-framed building with sufficient lengths of shear walls evenly distributed throughout the floor plan in both directions. Steel strap roof bracing in the roof plane. There were no negative factors influencing the performance. The building has been well constructed, and has been maintained in good condition with no deterioration.

Our IEP assessment of this building indicates it can achieve potential score of **100%NBS** in both the longitudinal and transverse directions. The IEP assessment of the building therefore indicates an overall score of **100%NBS**, corresponding to a **Grade A** building as defined by the New Zealand Society for Earthquake Engineering building grading scheme.

This is above the threshold for earthquake risk buildings (67%NBS) as recommended by the NZSEE. The key assumptions made during our assessment are shown in Table 1. Refer also to the attached IEP assessment.

3.2 IEP Grades and Relative Risk

Table 1 taken from the NZSEE Guidelines provides the basis of a proposed grading system for existing buildings, as one way of interpreting the %NBS building score. It can be seen that occupants in Earthquake Prone buildings (less than 34%NBS) are exposed to more than 10 times the risk that they would be in a similar new building. For buildings that are Earthquake

Risk (less than 67%NBS), but not Earthquake Prone, the risk is at least 5 times greater than that of an equivalent new building. Broad descriptions of the life-safety risk can be assigned to the building grades as shown in Table 2.

Table 2: Relative Earthquake Risk

Building Grade	Percentage of New Building Standard (%NBS)	Approx. Risk Relative to a New Building	Life-safety Risk Description
A+	>100	<1	low risk
A	80 to 100	1 to 2 times	low risk
B	67 to 79	2 to 5 times	low or medium risk
C	34 to 66	5 to 10 times	medium risk
D	20 to 33	10 to 25 times	high risk
E	<20	more than 25 times	very high risk

This building has been classified by the IEP as a **Grade A building** and is therefore considered to be a **low risk** structure.

The New Zealand Society for Earthquake Engineering (which provides authoritative advice to the legislation makers, and should be considered to represent the consensus view of New Zealand structural engineers) classifies a buildings achieving greater than 67%NBS as “Low Risk”, and having “Acceptable (improvement may be desirable)” building structural performance.

3.3 Seismic Restraint of Non-Structural Items

During an earthquake, the safety of people can be put at risk due to non-structural items falling on them. These items should be adequately seismically restrained, where possible, to the NZS 4219:2009 “The Seismic Performance of Engineering Systems in Buildings”.

An assessment has not been made of the bracing of the ceilings, in-ceiling ducting, services and plant. We have also not checked whether tall or heavy furniture has been seismically restrained or not. These issues are outside the scope of this initial assessment but could be the subject of another investigation.

4. Recommendations

The completed assessment gives a %NBS of >33 % and therefore, the **building should not be classed as potentially earthquake prone**.

The ISA is considered to provide a relatively quick, high-level and qualitative measure of the building’s performance. In order to confirm the seismic performance of this building with more reliability you may wish to request a DSA.

A DSA would also investigate other potential weaknesses that may not have been considered in the initial seismic assessment.

We trust this satisfies your requirements at this stage, however please contact the undersigned should you require any further information.

Appendices

Appendix A – Structural System Summary

Table 3 – Assessment Information

2. Assessment Information	
Consulting Practice	
CPEng Responsible, including: <ul style="list-style-type: none"> • Name • CPEng number • A statement of suitable skills and experience in the seismic assessment of existing buildings¹ 	
Documentation reviewed, including: <ul style="list-style-type: none"> • date/ version of drawings/ calculations² • previous seismic assessments 	<ul style="list-style-type: none"> • Original drawings dated 1983 • Drawings of alteration work dated 1995 and 2003
Geotechnical Report(s)	Site subsoil type is based on GNS Wellington Region Site Subsoil Maps
Date(s) Building Inspected and extent of inspection	Date of initial seismic assessment inspection: 14/06/2018
Description of any structural testing undertaken and results summary	N/A
Previous Assessment Reports	N/A
Other Relevant Information	N/A

¹ This should include reference to the engineer’s Practice Field being in Structural Engineering, and commentary on experience in seismic assessment and recent relevant training

² Or justification of assumptions if no drawings were able to be obtained

Table 4 – Structural System Summary for Wainuiomata Library

Number of Storeys	1 storey
Gross Floor Area (m ²)	Approx. 970 m ²
Year of Design (approximate)	1983, drawings available from September 1983.
Current use	Library
Importance Level (IL)	IL2 <ul style="list-style-type: none"> • The building is a public building but not a public assembly building. • The building is not designated as post-disaster function
Structural Alterations	Building appears to be designed and built in 1983. Alterations to building interior were carried out in 1995 and 2015.
Basement	None
Gravity Load Resisting System	Lightweight timber roof supported by timber frame walls
Lateral Load Resisting System	The lateral loads from roof self-weight are transferred to in-plane walls in both transverse and longitudinal directions.
Wall/Cladding/Roof System	Three types of roof cladding include galvanized corrugated iron, dimondek 400 tray roofing, and Butynol lined plate. External wall cladding comprises brick veneer cladding and fibre-cement sheet cladding on timber framed walls.
Floor System	Slab on grade
Foundation System	Slab on grade
Geotechnical Considerations	Based on GNS Wellington Region Site Subsoil Maps the subsoil classification for the site is considered to be Class D in accordance with NZS1170.5:2004.

Appendix B Initial Evaluation Form

Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in the "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Street Number & Name:	Queens Street, Wainuiomata	Job No.:	5137964
AKA:		By:	RC
Name of building:	Wainuiomata Library	Date:	21/06/2018
City:	Wainuiomata, Wellington	Revision No.:	1

Table IEP-1 Initial Evaluation Procedure Step 1

Step 1 - General Information

1.1 Photos (attach sufficient to describe building)




North-west view



North-east view

NOTE: THERE ARE MORE PHOTOS ON PAGE 1a ATTACHED

1.2 Sketches (plans etc, show items of interest)



NOTE: THERE ARE MORE SKETCHES ON PAGE 1a ATTACHED

1.3 List relevant features (Note: only 10 lines of text will print in this box. If further text required use Page 1a)

The Wainuiomata library is a single-storey timber-framed building, which was designed and constructed circa 1983. The building foundation is comprised of a concrete slab-on-grade. The external wall cladding is a combination of fibre-cement sheet cladding and brick veneer.

Alterations to the internal layout of the building were carried out in 1995 and 2015. The 1995 alteration included the construction of the ramp to improve the accessibility to the building and the removal of a number of timber walls (these were replaced with lintels and SHS columns). The 2015 alteration included adding a small lobby to the north-east side of the library.

Structural features of the building are listed below:

1. Timber roof trusses (exposed, ie: no ceiling)
2. Pryda-speedbrace roof bracing (steel strap bracing)
3. 9mm particle board wall bracing panels in both the longitudinal and transverse directions
4. Steel portal frames in the transverse direction in the Council Chamber (South-West corner of the building).

1.4 Note information sources

Tick as appropriate

Visual Inspection of Exterior	<input checked="" type="checkbox"/>
Visual Inspection of Interior	<input checked="" type="checkbox"/>
Drawings (note type)	<input checked="" type="checkbox"/>

Specifications	<input type="checkbox"/>
Geotechnical Reports	<input checked="" type="checkbox"/>
Other (list)	<input type="checkbox"/>

Drawings dated 1983; Alteration work drawings dated 1995 and 2003.
 Site subsoil type is based on GNS Wellington Region Site Subsoil Maps.

Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

Street Number & Name:	Queens Street, Wainuiomata	Job No.:	5137964
AKA:		By:	RC
Name of building:	Wainuiomata Library	Date:	21/06/2018
City:	Wainuiomata, Wellington	Revision No.:	1

Table IEP-2 Initial Evaluation Procedure Step 2

Step 2 - Determination of (%NBS)_b

(Baseline (%NBS) for particular building - refer Section B5)

2.1 Determine nominal (%NBS) = (%NBS)_{nom}

a) Building Strengthening Data

Tick if building is known to have been strengthened in this direction

If strengthened, enter percentage of code the building has been strengthened to

Longitudinal

Transverse

N/A

N/A

b) Year of Design/Strengthening, Building Type and Seismic Zone

- Pre 1935
- 1935-1965
- 1965-1976
- 1976-1984
- 1984-1992
- 1992-2004
- 2004-2011
- Post Aug 2011

- Pre 1935
- 1935-1965
- 1965-1976
- 1976-1984
- 1984-1992
- 1992-2004
- 2004-2011
- Post Aug 2011

Building Type: Others

Building Type: Others

Seismic Zone: Zone A

Seismic Zone: Zone A

c) Soil Type

From NZS1170.5:2004, CI 3.1.3 :

D Soft Soil

D Soft Soil

From NZS4203:1992, CI 4.6.2.2 :
(for 1992 to 2004 and only if known)

Not applicable

Not applicable

d) Estimate Period, T

Comment:

h_n = 4.5
A_c = 1.00

4.5 m
1.00 m²

- Moment Resisting Concrete Frames: $T = \max\{0.09h_n^{0.75}, 0.4\}$
- Moment Resisting Steel Frames: $T = \max\{0.14h_n^{0.75}, 0.4\}$
- Eccentrically Braced Steel Frames: $T = \max\{0.08h_n^{0.75}, 0.4\}$
- All Other Frame Structures: $T = \max\{0.06h_n^{0.75}, 0.4\}$
- Concrete Shear Walls: $T = \max\{0.09h_n^{0.75}/A_c^{0.5}, 0.4\}$
- Masonry Shear Walls: $T \leq 0.4\text{sec}$
- User Defined (input Period):

Where h_n = height in metres from the base of the structure to the uppermost seismic weight or mass.

T: 0.40

0.40

e) Factor A: Strengthening factor determined using result from (a) above (set to 1.0 if not strengthened)

Factor A: 1.00

1.00

f) Factor B: Determined from NZSEE Guidelines Figure 3A.1 using results (a) to (e) above

Factor B: 0.20

0.20

g) Factor C: For reinforced concrete buildings designed between 1976-84 Factor C = 1.2, otherwise take as 1.0.

Factor C: 1.00

1.00

h) Factor D: For buildings designed prior to 1935 Factor D = 0.8 except for Wellington and Napier (1931-1935) where Factor D may be taken as 1.0, otherwise take as 1.0.

Factor D: 1.00

1.00

(%NBS)_{nom} = Ax BxCxD

(%NBS)_{nom} 20%

20%

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

Street Number & Name:	Queens Street, Wainuiomata	Job No.:	5137964
AKA:		By:	RC
Name of building:	Wainuiomata Library	Date:	21/06/2018
City:	Wainuiomata, Wellington	Revision No.:	1

Table IEP-2 Initial Evaluation Procedure Step 2 continued

2.2 Near Fault Scaling Factor, Factor E

If $T \leq 1.5\text{sec}$, Factor E = 1

a) Near Fault Factor, $N(T,D)$

(from NZS1170.5:2004, Cl 3.1.6)

Longitudinal

$N(T,D)$: 1

Transverse

1

b) Factor E

= $1/N(T,D)$

Factor E: 1.00

1.00

2.3 Hazard Scaling Factor, Factor F

a) Hazard Factor, Z, for site

Location: Wainuiomata Refer right for user-defined locations

Z =	0.4	(from NZS1170.5:2004, Table 3.3)
Z_{1992} =	1.2	(NZS4203:1992 Zone Factor from accompanying Figure 3.5(b))
Z_{2004} =	0.4	(from NZS1170.5:2004, Table 3.3)

b) Factor F

For pre 1992 = $1/Z$
 For 1992-2011 = Z_{1992}/Z
 For post 2011 = Z_{2004}/Z

Factor F: 2.50

2.50

2.4 Return Period Scaling Factor, Factor G

a) Design Importance Level, I

(Set to 1 if not known. For buildings designed prior to 1965 and known to be designed as a public building set to 1.25. For buildings designed 1965-1976 and known to be designed as a public building set to 1.33 for Zone A or 1.2 for Zone B. For 1976-1984 set I value.)

Not Known

I = 1

Not Known

1

b) Design Risk Factor, R_o

(set to 1.0 if other than 1976-2004, or not known)

Item 1

R_o = 1

Item 1

1

c) Return Period Factor, R

(from NZS1170.0:2004 Building Importance Level)

Choose Importance Level

1 2 3 4

R = 1.0

1 2 3 4

1.0

d) Factor G

= IR_o/R

Factor G: 1.00

1.00

2.5 Ductility Scaling Factor, Factor H

a) Available Displacement Ductility Within Existing Structure

Comment:

Light-weight timber-framed structure which was designed in 1983.

μ = 2.00

2.00

b) Factor H

For pre 1976 (maximum of 2) = k_μ
 For 1976 onwards = 1

Factor H: 1.00

1.00

(where k_μ is NZS1170.5:2004 Inelastic Spectrum Scaling Factor, from accompanying Table 3.3)

2.6 Structural Performance Scaling Factor, Factor I

a) Structural Performance Factor, S_p

(from accompanying Figure 3.4)

Tick if light timber-framed construction in this direction

S_p = 0.50

0.50

b) Structural Performance Scaling Factor

= $1/S_p$

Factor I: 2.00

2.00

Note Factor B values for 1992 to 2004 have been multiplied by 0.67 to account for S_p in this period

2.7 Baseline %NBS for Building, (%NBS)_b

(equals (%NBS)_{nom} x E x F x G x H x I)

100%

100%

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

Street Number & Name:	Queens Street, Wainuiomata	Job No.:	5137964
AKA:		By:	RC
Name of building:	Wainuiomata Library	Date:	21/06/2018
City:	Wainuiomata, Wellington	Revision No.:	1

Table IEP-3 Initial Evaluation Procedure Step 3

Step 3 - Assessment of Performance Achievement Ratio (PAR)

(Refer Appendix B - Section B3.2)

a) Longitudinal Direction

potential CSWs	Effect on Structural Performance (Choose a value - Do not interpolate)	Factors
3.1 Plan Irregularity Effect on Structural Performance <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant Light-weight timber-framed building, the plan irregularity is assumed to be insignificant.		Factor A 1.0
3.2 Vertical Irregularity Effect on Structural Performance <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant Single storey building - no vertical irregularity		Factor B 1.0
3.3 Short Columns Effect on Structural Performance <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant N/A		Factor C 1.0
3.4 Pounding Potential (Estimate D1 and D2 and set D = the lower of the two, or 1.0 if no potential for pounding, or consequences are considered to be minimal)		

a) Factor D1: - Pounding Effect

Note:
 Values given assume the building has a frame structure. For stiff buildings (eg shear walls), the effect of pounding may be reduced by taking the coefficient to the right of the value applicable to frame buildings.

Factor D1 For Longitudinal Direction: 1.0

Table for Selection of Factor D1	Severe 0<Sep<.005H	Significant .005<Sep<.01H	Insignificant Sep>.01H
Alignment of Floors within 20% of Storey Height	<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8

Comment

b) Factor D2: - Height Difference Effect

Factor D2 For Longitudinal Direction: 1.0

Table for Selection of Factor D2	Severe 0<Sep<.005H	Significant .005<Sep<.01H	Insignificant Sep>.01H
Height Difference > 4 Storeys	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 1
Height Difference 2 to 4 Storeys	<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys	<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1

Comment

Factor D 1.0

3.5 Site Characteristics - Stability, landslide threat, liquefaction etc as it affects the structural performance from a life-safety perspective

Effect on Structural Performance <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant	Factor E	1.0
GNS Wellington Region Liquefaction Map shows that moderate liquefaction risk for this site. The building is considered as resilient structure type as it is a single-storey building.		

3.6 Other Factors - for allowance of all other relevant characteristics of the building

For ≤ 3 storeys - Maximum value 2.5
 otherwise - Maximum value 1.5.
 No minimum.

Factor F 1.0

Record rationale for choice of Factor F:

Single-storey light-weight timber-framed structure with sufficient lengths of shear walls evenly distributed throughout the floor plan in both directions. Steel strap roof bracing has been installed in the roof plane. There were no negative factors such as CSWs. The building has been well constructed, and has been maintained in good condition with no deterioration.

3.7 Performance Achievement Ratio (PAR)

(equals A x B x C x D x E x F)

PAR
Longitudinal 1.00

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

Street Number & Name:	Queens Street, Wainuiomata	Job No.:	5137964
AKA:		By:	RC
Name of building:	Wainuiomata Library	Date:	21/06/2018
City:	Wainuiomata, Wellington	Revision No.:	1

Table IEP-3 Initial Evaluation Procedure Step 3

Step 3 - Assessment of Performance Achievement Ratio (PAR)

(Refer Appendix B - Section B3.2)

b) Transverse Direction

potential CSWs	Effect on Structural Performance (Choose a value - Do not interpolate)	Factors
3.1 Plan Irregularity <i>Effect on Structural Performance</i> <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant Light-weight timber-framed building, the plan irregularity is assumed to be insignificant.		Factor A 1.0
3.2 Vertical Irregularity <i>Effect on Structural Performance</i> <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant Single storey building, no vertical irregularity		Factor B 1.0
3.3 Short Columns <i>Effect on Structural Performance</i> <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant N/A		Factor C 1.0
3.4 Pounding Potential (Estimate D1 and D2 and set D = the lower of the two, or 1.0 if no potential for pounding, or consequences are considered to be minimal)		

a) Factor D1: - Pounding Effect

Note:
Values given assume the building has a frame structure. For stiff buildings (eg shear walls), the effect of pounding may be reduced by taking the coefficient to the right of the value applicable to frame buildings.

Factor D1 For Transverse Direction: 1.0

Table for Selection of Factor D1	Severe	Significant	Insignificant
	0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Alignment of Floors within 20% of Storey Height	<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8
Comment			

b) Factor D2: - Height Difference Effect

Factor D2 For Transverse Direction: 1.0

Table for Selection of Factor D2	Severe	Significant	Insignificant
	0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Height Difference > 4 Storeys	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 1
Height Difference 2 to 4 Storeys	<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys	<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1
Comment			

Factor D 1.0

3.5 Site Characteristics - Stability, landslide threat, liquefaction etc as it affects the structural performance from a life-safety perspective

<i>Effect on Structural Performance</i> <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant	Factor E 1.0
GNS Wellington Region Liquefaction Map shows that moderate liquefaction risk for this site. The building is considered as resilient structure type, as it is a single-storey building.	

3.6 Other Factors - for allowance of all other relevant characteristics of the building

For ≤ 3 storeys - Maximum value 2.5
otherwise - Maximum value 1.5.
No minimum.

Factor F 1.00

Record rationale for choice of Factor F:
Single-storey light-weight timber-framed structure with sufficient lengths of shear walls evenly distributed throughout the floor plan in both directions. Steel strap roof bracing has been installed in the roof plane. There were no negative factors such as CSWs. The building has been well constructed, and has been maintained in good condition with no deterioration.

3.7 Performance Achievement Ratio (PAR)
(equals A x B x C x D x E x F)

PAR
Transverse 1.00

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

Street Number & Name:	Queens Street, Wainuiomata	Job No.:	5137964
AKA:		By:	RC
Name of building:	Wainuiomata Library	Date:	21/06/2018
City:	Wainuiomata, Wellington	Revision No.:	1

Table IEP-4 Initial Evaluation Procedure Steps 4, 5, 6 and 7

Step 4 - Percentage of New Building Standard (%NBS)

	Longitudinal	Transverse
4.1 Assessed Baseline %NBS (%NBS) _b (from Table IEP - 1)	100%	100%
4.2 Performance Achievement Ratio (PAR) (from Table IEP - 2)	1.00	1.00
4.3 PAR x Baseline (%NBS) _b	100%	100%
4.4 Percentage New Building Standard (%NBS) - Seismic Rating (Use lower of two values from Step 4.3)		100%

Step 5 - Is %NBS < 34?

NO

Step 6 - Potentially Earthquake Risk (is %NBS < 67)?

NO

Step 7 - Provisional Grading for Seismic Risk based on IEP

Seismic Grade **A**

Additional Comments (items of note affecting IEP based seismic rating)

Relationship between Grade and %NBS:

Grade:	A+	A	B	C	D	E
%NBS:	> 100	100 to 80	79 to 67	66 to 34	< 34 to 20	< 20

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

Street Number & Name:	Queens Street, Wainuiomata	Job No.:	5137964
AKA:		By:	RC
Name of building:	Wainuiomata Library	Date:	21/06/2018
City:	Wainuiomata, Wellington	Revision No.:	1

Table IEP-5 Initial Evaluation Procedure Step 8

Step 8 - Identification of potential Severe Structural Weaknesses (SSWs) that could result in significant risk to a significant number of occupants

- 8.1 Number of storeys above ground level 1
- 8.2 Presence of heavy concrete floors and/or concrete roof? (Y/N) N

Potential Severe Structural Weaknesses (SSWs):

Note: Options that are greyed out are not applicable and need not be considered.


Occupancy not considered to be significant - no further consideration required

Risk not considered to be significant - no further consideration required


The following potential Severe Structural Weaknesses (SSWs) have been identified in the building that could result in significant risk to a significant number of occupants:

1. None identified
2. Weak or soft storey (except top storey)
3. Brittle columns and/or beam-column joints the deformations of which are not constrained by other structural elements
4. Flat slab buildings with lateral capacity reliant on low ductility slab-to-column connections
5. No identifiable connection between primary structure and diaphragms
6. Ledge and gap stairs

IEP Assessment Confirmed by



WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.



Initial Evaluation Procedure (IEP) Assessment - Completed for Hutt City Council

Street Number & Name:	Queens Street, Wainuiomata	Job No.:	5137964
AKA:		By:	RC
Name of building:	Wainuiomata Library	Date:	21/06/2018
City:	Wainuiomata, Wellington	Revision No.:	1



Table IEP-1a Additional Photos and Sketches

Add any additional photographs, notes or sketches required below:


Note: print this page separately



North-east view of building



Longitudinal section view



Transverse section view

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

