
## Wellington Region Path back to fluoridation

Waterloo		Wainuiomata	
DOSING	Current Fluoride dosing equipment operable but can't fluoridate the	DOSING	Current Fluoride dosing equipment operable
RELIABILITY	amount of water Waterloo produces.	RELIABILITY	radiac dosing equipment operation
DOSING	Short-term – 1 month System control optimization.	DOSING	Short-term – 1 month system control optimization.
RELIABILITY		RELIABILITY	
DOSING RELIABILITY	Medium-term – 6 months Ongoing maintenance and increase of spare parts held	DOSING RELIABILITY	Medium-term – 6 months Ongoing maintenance and increase of spare parts held
DOSING RELIABILITY	Long-term – 12 months+ Replace fluoridation plant. 1-3 years.	DOSING RELIABILITY	Long-term – 12 months+ Replace fluoridation plant. 1-3 years
Gear Island		Te Marua	
DOSING RELIABILITY	Current Fluoride room has structural concerns making the room unsafe for operators – survey of room underway Fluoride plant condition assessment underway	DOSING RELIABILITY	Current Divers booked to assess Baffle Curtain Reinstate Fluoride plant - historically equipment unreliable New Baffle Curtain ordered
DOSING RELIABILITY	Short term - 1 month  Make fluoride dosing room safe.  Commence Repairs to Fluoride system or source external containerized solution.	DOSING RELIABILITY	Short term – 1 month If possible complete repair of curtain, Restart fluoridation plant
DOSING RELIABILITY	Medium term – 6 months  Ongoing maintenance and sourcing of critical spares. Additional dosing safeguards  Close Gear Island and expand Waterloo capacity#	DOSING RELIABILITY	.  Medium term – 6 months+  Ongoing maintenance and sourcing of critical spares  New Baffle Curtain installed
DOSING RELIABILITY	Long-term – 12 months+ Replace fluoridation plant.	DOSING RELIABILITY	Long term – 12 months+ Options assessment, design procure and build new fluoridation plant
# This would require relevant council decision to fluoridate Petone and Korokoro			



Greater Wellington wholesale water supply network