

Hutt City Council 30 Laings Road Private Bag 31912 Lower Hutt 5040 New Zealand

www.huttcity.govt.nz

T 04 570 6666 F 04 569 4290

20 October 2022

Annah Casey-Solly Morrison Kent

### Tēnā koe Annah Request for Information – Local Government Official Information and Meetings Act (LGOIMA) 1987

We refer to your official information request dated 22 September 2022, for the following:

- "...any information the Hutt City Council holds, from 1 January 2022 to date, relating to any landslides and/or erosion issues at the following properties/land in Lower Hutt:
- the properties between 14 and 18 Korokoro Road inclusive;
- the properties between 34 and 38 Korokoro Road inclusive;
- 10 Singers Road;
- 16 Singers Road, including where it meets Korokoro Road; and
- 8 Pito-One Road

In particular, we request any and all correspondence, files, records, maps, drawings, images and/or project information relating to landslides, slips, erosion or land stability issues at the above properties.

Further, if there have been any significant landslides or erosion events prior to January 2022 at the above properties, please let us know and we will amend our request accordingly."

The information you have requested is enclosed.

We have enclosed excerpts of LIM reports for 18 and 38 Korokoro Road. These LIM reports were prepared early in 2022. We are able to provide this information to you under the LGOIMA however, unless the reports were purchased by homeowners that you are representing legally, they may not be accepted for finance or insurance purposes. Further, the information that has or has not been included in the report is unable to be challenged.

It is also important to note that the LIM reports will not include information generated after the issue date for the LIM, so will not include recent flood or slip information, district plan changes or recent consents or consent documents. Accordingly, we have attached an email chain and photographs associated with the September 2022 slips.

Please also note that some personal information has been redacted from the LIM excerpts under section 7(2)(a), to protect the privacy of individuals. In doing so, we considered the public interest in making the information available and have determined that it does not outweigh the need to protect the privacy of these persons.

You have the right to seek an investigation and review by the Ombudsman of this response. Information about how to make a complaint is available at www.ombudsman.parliament.nz or freephone 0800 802 602.

Please note that this letter may be published on the Council's website.

Nāku noa, nā

Solo

Susan Sales Senior Advisor, Official Information and Privacy

Encl: Email chain 2 September 2022 slip and slip photographs Excerpt LIM220005 – 38 Korokoro Road (7 February 2022) Excerpt LIM2101215 – 18 Korokoro Road (15 January 2022) From: Paul Pugh <Paul.Pugh@huttcity.govt.nz>

Sent on: Friday, September 2, 2022 1:23:26 AM

To: Charlie Deed <Charlie.Deed@huttcity.govt.nz>

CC: Jason Macnee <Jason.Macnee@huttcity.govt.nz>

Subject: RE: Korokoro Rd slip

Awesome thanks Charlie

From: Charlie Deed <Charlie.Deed@huttcity.govt.nz>
Sent: Friday, 2 September 2022 1:22 pm
To: Paul Pugh <Paul.Pugh@huttcity.govt.nz>
Cc: Jason Macnee <Jason.Macnee@huttcity.govt.nz>
Subject: RE: Korokoro Rd slip

Hey Paul

Road closed at time of inspection from the car park below. Some Minor slips along the road had already been cleared. Main Slip being cleared while on site.

I walked up to no. 16 Korokoro Rd and it is far enough away from the slip. I struggled to get good access to Singers Rd but 16 Singer Road appears far enough away not to be affected, when looking at it from further up Korokoro road. Rough location shown below.



**Cheers Charlie** 

Charlie Deed Senior Building Officer (Inspections) From: Jason Macnee <Jason.Macnee@huttcity.govt.nz>
Sent: Friday, 2 September 2022 9:49 AM
To: Charlie Deed <<u>Charlie.Deed@huttcity.govt.nz</u>>
Subject: FW: Korokoro Rd slip

Hey mate,

Thanks for this.

Cheers,

Jason Macnee Senior Building Officer

Hutt City Council, 30 Laings Road, Lower Hutt 5040 P: M: 027 248 3606 W: www.huttcity.govt.nz

From: Paul Pugh <<u>Paul.Pugh@huttcity.govt.nz</u>>
Sent: Friday, 2 September 2022 9:39 AM
To: Jason Macnee <<u>Jason.Macnee@huttcity.govt.nz</u>>
Cc: Jon Kingsbury <<u>Jon.Kingsbury@huttcity.govt.nz</u>>
Subject: RE: Korokoro Rd slip

Hi Jason

To clarify if there are no concerns do not go up to the houses, only go to the house if the inspector can see anything of concern.

Cheers Paul

From: Paul Pugh
Sent: Friday, 2 September 2022 9:26 am
To: Jason Macnee <Jason.Macnee@huttcity.govt.nz>
Cc: Jon Kingsbury <Jon.Kingsbury@huttcity.govt.nz>
Subject: Korokoro Rd slip

Hi Jason

As discussed just now on the phone can you get one of the team to have a look at 16/18 Korokoro Rd to see if the houses are affected in any way with the slip that happened yesterday. Jon Kingsbury from our transport team has let me know they are dealing with the engineering on the slip so for us it's to see if we have any concerns.

Whoever you send can you please make sure they take any notes or pictures that may be relevant for now? Can you ask they get this done this morning please if possible all dependant on their booked inspections.

Thanks in advance Paul


Paul Pugh Building Manager Hutt City Council, 30 Laings Road, Lower Hutt 5010 P: M: 027 287 0319 W: www.huttcity.govt.nz



Main slip 1, 2022



Minor slip along Korokoro Road 1, 2022



Minor slip along Korokoro Road 2, 2022





Minor slip under concrete steps along Korokoro Rd, 2022



# LIM220005 excerpts - 38 Korokoro Road

#### FLOODING (INUNDATION, ALLUVION\*, AVULSION\*\*)

\* The wash of the sea or of a river. \*\*Sudden loss of soil from flood or from shift in course of stream.

Council holds no information about reported instances of flooding on the property. In 1976, flooding at the neighbouring property 18 Korokoro Road was reported to the council.

Flood risk modelling investigations are being compiled for Lower Hutt suburbs, including Wainuiomata, Stokes Valley and more. If you require further information, please contact Wellington Water on 04 912 4400.

#### SLOPE STABILITY (SLIPPAGE, FALLING DEBRIS, EROSION AND SUBSIDENCE)

Council holds no record of any erosion on the property.

In 2002 & 2005, slip at the property and nearby area was reported to the council. Please see the Enquiry Trace Forms attached.


#### EARTHQUAKE HAZARDS

Information relating to liquefaction, ground shaking, active faults and slope failure can be found on Greater Wellington Regional Council's Hazards and Emergency Management Maps.

#### **CO-SEISMIC SUBSIDENCE**

For information on estimated subsidence of the valley floor during a Wellington Fault rupture, the GNS Science Report *Estimating co-seismic subsidence in the Hutt Valley associated with rupture of the Wellington Fault* is available to download from the following website http://shop.gns.cri.nz/estimating-co-seismic-subsidence-in-the-hutt-valley-associated-with-rupture-of-

the-wellington-fault/



Although the information displayed has been prepared with care and in good faith, It is an information service and is designed to be illustrative only. The Council cannot guarantee the accuracy or completeness of the information and accepts no liability for any loss suffered as a result of reliance on the information. Parcel boundaries sourced from Land Information New Zealand data supplied under licence to Hutt City Council. Crown Copyright Reserved

16/02/2016		1.0				
Enquiry: 6354	0	Logged by:	Ollie Denzler (8888			on 10/01/2005 16:3
Service: Wat			Clas	sification: Request	For Service	
Subject: No V			t deine ee e woter ni	a has some apart h	nas happened before -	ha naade sama ana tr
Desc.: com	e and join it up ag	ain-he has turn	ed off the valve so no	water.	las happened belore -	ne needs some one d
	koro Road (R007	67), Korokoro, I	ower Hutt			
Site Address: Koro Location: 38 k					ea: Korokoro rd: Harbour	
Location: 30 K				Wa		
		1				
Customer: 6196	57	Time: 10	/01/2005 16:39		od: phone call	
Name: - Address:				Telephor	ne: ion and h	
Current Status:					0 Contraction of the second se	1.5
No. Effective	Status		Officer	2	Follow up D	ate
3 31/01/2005 04:2 Notes: Repai	3:37   Call Closed red service 10/1/0		Excell W	ater Supply		
itatus history:			land?		1.0.7.7	
No. Effective	Status	0	Officer	the Current	Notes	
2 11/01/2005 08:4 1 10/01/2005 16:3				ater Supply ater Supply		
Deviced Statuc				ator ouppij		
aleased und						

Name : ..... Date : ..... Time :<sub>47</sub>.....

### 16/02/2016

Service: Water St		Classification: Reques	t For Service
Subject: Leaks - \			
Desc.: clipped a	a pipe while clearing a slip on the	driveway	
Site: Korokoro	Road (R00767), Korokoro, Low	er Hutt	
Site Address: Korokoro	Road	А	rea: Korokoro
Location: 36-38 Ko	prokoro Road	w	ard: Harbour
Customer: 15365	Time: 11/03/	2002 11:50 Meth	nod: phone call
Name:			
Address:			
			AND I HAVE A
urrent Status:	Status	Officer	Follow up Date
No. Effective 3 12/03/2002 11:53:58		Excell Water Supply	Pollow up Date
	epaired service - 11/03/02	Excell Water Supply	
tatus history:			
No. Effective	Status	Officer	Notes
2 11/03/2002 15:22	Passed to Contractor	Excell Water Supply	
1 11/03/2002 11:50	Call Logged	Excell Water Supply	
Revised Status:			

# LIM2101215 excerpt - 18 Korokoro Road

#### FLOODING (INUNDATION, ALLUVION\*, AVULSION\*\*)

\* The wash of the sea or of a river. \*\*Sudden loss of soil from flood or from shift in course of stream.

Council records show flooding has been reported at the property in 1976. Please see the attachments.

Flood risk modelling investigations are being compiled for Lower Hutt suburbs, including Wainuiomata, Stokes Valley and more. If you require further information, please contact Wellington Water on 04 912 4400.

#### SLOPE STABILITY (SLIPPAGE, FALLING DEBRIS, EROSION AND SUBSIDENCE)

Council records show slippage has been reported at this property and in the nearby areas in 1976, 2002, 2004, 2015, 2016, 2017 and 2018. Please see the Enquiry Trace Forms attached.


Council records show there has been slippage/erosion on the neighbouring property 12 Singers Road in 1993, 1995, 2012 and 2017.

#### EARTHQUAKE HAZARDS

Information relating to liquefaction, ground shaking, active faults and slope failure can be found on Greater Wellington Regional Council's Hazards and Emergency Management Maps.

#### **CO-SEISMIC SUBSIDENCE**

For information on estimated subsidence of the valley floor during a Wellington Fault rupture, the GNS Science Report *Estimating co-seismic subsidence in the Hutt Valley associated with rupture of the Wellington Fault* is available to download from the GNS website.



Although the information displayed has been prepared with care and in good faith, It is an information service and is designed to be illustrative only. The Council cannot guarantee the accuracy or completeness of the information and accepts no liability for any loss suffered as a result of reliance on the information. Parcel boundaries sourced from Land Information New Zealand data supplied under licence to Hutt City Council. Crown Copyright Reserved

LOWER HUTT CITY CORPORATION FLOOED RELIEF HELP WANTER 269 FINANCIAL 3 Class: FINANCIAL AND ACCOMMODATION FINANCIAL AND CLOTHING & FURNITURE CLOTHING ONLY FURNITURE ONLY TRAVELLING EXPENSES PHYSICAL - MECHANICAL PHYSICAL - OTHER Date Applied: Name : Plat 3 18 Korokon Rd Petone Address: Tel No.: Family:  $\mathbf{k}_{i}^{*}$ Post office Place of Work Contact (bank, relative etc) Name & Address Bank at back Slipped and water is Depring unde Particulars Capital home wild like help po Assets 3 mon to took have & sti try the orga for haddress has booked to overseas on 14/11 Componnership - 6 people I declare the above information is true Applicants signature ..... Workers Signature ..... 124

Flat 6 18 KORD KORD RD 270 PETONE Dear Sir working to matre application for aid available from I Fut Valley Flood Relief Fund the a bad slip at the rear of my propert had have White recieved no danage to my flat T I have have amount. amount the problem now O brotten fence and cloth line. at present I will be busy moving mud etc. for time six week tle next as I can do nost of the north myself the rost be minimal there lothes line and also repair chainson need atarge tree. The cost involved r cmove nould be approx \$100 to be married th the am weeks Six without the offord here are all I expenses involved expense additional above are probably those worse off than there real ise still available I would appreciate myselt asistence that can be given. any yours faithfully 1 ( 3.3 Item 503 53524D-41,000 pads/10/74

#### 14/01/2022


En antina d	04005	1					40/00/	0040 44 07
Enquiry: 4		Logged by						2018 11:27
	load and Traffic			Classi	fication: F	Request For Se	rvice	
-	lip Maintenance				c 7(2)(a			
	ee rfs # 420989 2 x s o sort - north & south			ир бу	s 7(2)(a	- B	UT two larger slips need F	ulton Hogar
	orokoro Road (R0076	67), Korokoro	, Lower Hutt					
Site Address: K						Area: Kor		
Location: 1	8 korokoro road					Ward: Har	bour	
						Contact:		
							-	S?
		Time: (	8/09/2018 10	):48		Method	Aix I	
Name:								
Address:								
Current Status:						A.		
No. Effective	Status			Officer			Follow up Date	
	2:20:52 Call Closed			Fulton Hoga	an Ltd 🆕			
Notes: ⊢⊟ Status history:	- Slip Cleared 10/09/	2018			- (Î			
No. Effective	Status			Officer			Notes	
2 10/09/2018 1		1		Fulton Hoga	an I td		Notes	
1 10/09/2018 1				Fulton Hoga			logged as per <mark>s 7(2)(a)</mark>	
Davis ed Otature							s 7(2) instructions	
Revised Status:								

14/01/2022		E	Enquiry Trace Form		
Enquiry: 388	3118	Logged by:	Carol Thompson	0	n 01/09/2017 10:4
Service: Ro	ad and Traffic		Classification	: Request For Service	
Subject: Slip	o Maintenance				
sor you Ko	meone to check this u can only see it fror rokoro Road - big sl	out and ensur n Hutt Road ip on half of the	e that the house is not going to e road and debris on other half.	bove the slip and caller can see the come down with the slip or how clo At least a truckload of dirt - still fall st saw it come down, just missed h	se it is to the slip – ing. At least halfwa
Site: Ko	rokoro Road (R0076	67), Korokoro, I	Lower Hutt		
Site Address: Ko		,.		Area: Korokoro	
Location: Up	hill near 18 Korokor	o Road		Ward: Harbour	
				Contact	
				Alternate:	
Customer:		<b>Time:</b> 01	/09/2017 10:45	Method: IRAP	ins
Name:				Alternate:	
Address:					
Current Status: No. Effective	Status		Officer	Follow up Dat	e
	59:45 ; Call Closed		Fulton Hogan Ltd		e
	Slip was cleared 01	/09/2017	T uttori Hogari Etu		
Status history:	<u></u>			<u>()</u>	
No. Effective	Status		Officer	Notes	
5 01/09/2017 11:	27 Passed to C	Contractor	Fulton Hogan Ltd	Big slip blockin road will need t until cleared.	
4 01/09/2017 11:	13 Call Logged		Fulton Hogan Ltd	Subject amend Urgent (ARUR) Maintenance ( S((9)) also assessing	) New : Slip ARSS). ng , Colin
3 01/09/2017 10	:45 Call Logged		Samantha Whittam	0	
2 01/09/2017 10	:54 Call Logged		Fulton Hogan Ltd	s7(2) to investi reported to s7(	gate and <sup>2)(a)</sup> at FH.
1 01/09/2017 10	:45 Call Logged	$\mathcal{C}$	Samantha Whittam	1	
Revised Status:					

### 14/01/2022

		_			
Enquiry:	363843	Logged by:	Julie Norriss (5706666)		on 15/11/2016 13:23
Service:	Road and Traffic	-	Classification	: Request For Service	
Subject:	Slip Maintenance				
-		covering one lan	e just downform #18 korokoro r	oad 3 areas volume c	ouple of ute loads on a blind
	corner so very dange	rous need signs	etc		
	Korokoro Road (R007	'67), Korokoro, I	₋ower Hutt		
	Korokoro Road			Area: Korokoro	
Location:	18 Korokoro Rd, KOF	ROKORO		Ward: Harbour	
				Contact:	
				Telephone:	
Customer:		<b>Time:</b> 15	/11/2016 13:23	Method: IRAP	
			11/2010 13.23		
Name:				Telephone	
Address:					
Current Status:					
No. Effective	Status		Officer	Follo	ow up Date
4 18/11/2016	11:11:06 a Call Closed	d	leshea McDonald		-
Notes: F	H attended to slips wh	nen reported.			
Status history:					
No. Effective	Status		Officer	Note	s
3 15/11/2016	16:09 Passed to	Contractor	leshea McDonald		orted to FH to
2 45/44/2040		d	leshea McDonald	inves	stigate.
2 15/11/2016 1 15/11/2016			leshea McDonald		
Revised Status:	13.23 Call Logge	u			
Reviseu Status.					

#### 14/01/2022



14/01/202					
Enc	<b>quiry:</b> 44711	Logged by:	Michelle Stone		on 02/02/2004 12:21
Ser	vice: Road and	d Traffic	Classification:	Request For Service	
Sut	bject: Slips on F	Private Property			
D	esc.: Slip on rig	ght hand side - just pass 18	Korokoro Road - phoned through	n to	
	Site: Korokoro	Road (R00767), Korokoro, I	ower Hutt		
	ress: Korokoro	· · · ·		Area: Korokoro	
		oro Road Korokoro		Ward:	
				Contact:	
				Telephone:	
Custo	omer:	<b>Time</b> : 02	/02/2004 12:21	Method:	kill <sup>o</sup>
N	ame:			Telephone:	
Add	ress:				
Current Statu		Otatura	0.0	<u></u>	Data
No. Effec		Status	Officer	Follow up	Date
	/2004 05:31:08	•	Colin Russell		
	up. Not on	all slip and at Tues 10 Feb h le for me. Belongs .Pass assess as discussed with R.	ed to s 7(2)	<u></u>	
Status history					
No. Effec	tive	Status	Officer	Notes	
4 04/02	2/2004 15:44	Call Logged	Colin Russell		Colin Russell to discussed with
				R. Muir	
3 04/02	2/2004 13:19	Passed to Contracts Office	er Colin Lunn		e same enquiry
				referring t ieshea	o RFS 44369.
2 02/02	2/2004 13:08	Passed to Contractor	leshea McDonald		Faxed Works.
1 02/02	2/2004 12:21	Call Logged	leshea McDonald	Thomas a	
Revised Stat	us:	- 55			
		Passed to Contracts Office Passed to Contractor Call Logged			

14/01	/2022
-------	-------

14/01/2022			Enquiry made Form	
Enquiry: 196	636	Logged by:	Ngawai Allen (6155)	on 16/07/2002 08:03
Service: Roa	ad and Traffic		Classification: R	equest For Service
Subject: Slip	o Maintenance			
			slips between the above - caller just e has her phone on voicemail.	said they are hard to see in the dark - no other
Site: Kor	rokoro Road (R0076	67), Korokoro, I	Lower Hutt	
Site Address: Kor	rokoro Road			Area: Korokoro
Location: 16	to 18 Korokoro Rd			Ward: Harbour
				Contact:
			Те	elephone:
Customer:		<b>Time:</b> 16	6/07/2002 08:03	Method:
Name:			Те	elephone:
Address:				No
Current Status:				
No. Effective	Status		Officer	Follow up Date
	30:28 ¿ Call Closed		John Middleton	
	s Infrastructure hav	e cleared		
Status history:	01-1		0///	No.4-
No. Effective	Status	1	Officer	Notes
1 16/07/2002 08: Revised Status:	:03 Call Logged		John Middleton	